

Men`s TX Performance Hooded Softshell Jacket



Measures in CMS

TO FIT APPROX CHEST SIZE	SIZE	S	M	L	XL	2XL	3XL	TOL +/-
	UK	38	41	44	47	50	53	
	EURO	48	50	54	56	60	64	
A	1/2 CHEST AT UNDERARM SEAM - LAY JACKET FLAT	58	60	62	64	66	68	1
B	BACK LENGTH	70	72	74	76	78	80	1
C	SHOULDER / SLEEVE LENGTH (TAKEN FROM SIDE NECK SEAM)	79	81	83	85	87	89	1

